



G114 Footwell/defrost flap motor position sensor

- on left side of heater box, above footwell outlet; integral with flap motor -V85-