



G92 Temperature flap motor position sensor

- on heater box, above central tunnel, right front
- integral with flap motor –V68–