



G66 Knock Sensor (KS) 2 (2.8 ltr. engine)

- below intake manifold, near left (bank 2) cylinder head
- shown with intake manifold removed